

11/5/25

# FTX-1 Firmware Update Information

Download the FTX-1 [FTX-1\_USA\_Firmware\_Update\_202511.zip] from the following website: <a href="https://www.yaesu.com/product-detail.aspx?Model=FTX-1%20Series&CatName=HF%20Transceivers/Amplifiers">https://www.yaesu.com/product-detail.aspx?Model=FTX-1%20Series&CatName=HF%20Transceivers/Amplifiers</a>

[FTX-1 Firmware update 202511]zip Contains:

• DISPLAY : FTX-1\_DISPLAY\_V0107.SFL (New)

• MAIN : FTX-1\_MAIN\_V0110.SFL (New)

• DSP : FTX-1\_IFDSP\_V0105.SFL (New)

• SDR : FTX-1\_SDR\_V0105.SFL (New)

• OPT : SPA-1\_CTRL\_V0113.SFL (New)

## <u>(FTX-1)</u>

| • | DISPLAY | $V01-06 \rightarrow V01-07$ |
|---|---------|-----------------------------|
| • | MAIN    | $V01-08 \rightarrow V01-10$ |
| • | DSP     | $V01-03 \rightarrow V01-05$ |
| • | SDR     | $V01-04 \rightarrow V01-05$ |

### (SPA-1)

• OPT  $V01-12 \rightarrow V01-13$ 

\*\*\*\*\*\*\*\*\*

Important: Please read the FTX-1 series Firmware Upgrade Manual, Firmware Ver Up Manual ENG FTX-1 2506-C.pdf


### **Implement improvements (November 2025):**

- Improved C4FM reception characteristics.
- Fixed an issue where it was not possible to stop message transmission by keying during the interval when repeatedly sending CW messages in Beacon Mode.
- Fixed an issue where the scope display would invert UPPER/LOWER when transmitting SSB on VHF.
- Fixed an issue where the CW indicator would stop illuminating.
- Improved operational stability in C4FM and APRS modes.
- Optimized the antenna tuning operation of the SPA-1.
- Minor fixes to OPERATION SETTING.
- Other minor fixes.

**Note:** After completely installing the firmware, the FTX-1 must be reset. Refer to the FTX-1 series Operating Manual Page 79. Or refer to the Firmware Ver Up Manual ENG FTX-1 2506-B

#### Reset the transceiver

- 1. Turn the transceiver OFF.
- 2. While pressing the [BACK] and [FINE/FAST] keys simultaneously, then turn the transceiver ON.
  - The frequency display will return to "144.000.000" (SUB-side), "7.000.000" (MAIN-side).



This completes the firmware upgrading process.

If you already have the above firmware versions, it is not necessary to update the FTX-1 again.

We hope this new firmware will increase your enjoyment of your FTX-1. Thank you for choosing Yaesu radios. If you have any problems or questions, please contact Yaesu Amateur Tech Support amateurtech@yaesu.com.

Yaesu USA | 6125 Phyllis Drive | Cypress, CA 90630 | 714.827-7600 | FAX: 714.827-8100 http://www.yaesu.com