



9/6/18

## WiRES-X PC Software Update Information

Refer to the **HRI-200 Software Update Instruction Manual** in each ZIP file.

Download the [ **wx1420en.zip**] from the website listed below.

<http://yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=108&encProdID=1D23D01F7B34D76072988D9857AA1A7C&DivisionID=65&isArchived=0>

WiRES-X (PC software) ver. 1.410 → ver. 1.420 correction details:

- In the operation of a ROOM, when transmission signals enter simultaneously from multiple NODE stations connected to the same ROOM, Fixed the problem that audio was doubling intermittently.
- In a ROOM with many connected stations, ROOM hangs up due to overflow. Improved the problem of unexpected audio disconnect and dropouts that occurred in a ROOM with many connections or overflow operation.
- Fixed a problem of the "OFFLINE" Status display at the bottom right of the main screen, even while "ONLINE" is running.

If you already have Ver. 1.420 software, it is not necessary to update again.

We hope this new software will increase your enjoyment of the WiRES-X. Thank you for choosing Yaesu radios. If you have any problems or questions please contact Yaesu Amateur Tech Support [amateurtech@yaesu.com](mailto:amateurtech@yaesu.com).