



6/26/19

## **FTDX101D Firmware Update Information**

Download the FTDX101D [FTDX101\_Firmware update\_201906.zip] from the following website:  
<http://yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=959169DE998192AB87295E90077D740D&DivisionID=65&isArchived=0>

### **FTDX101 Firmware update\_201906.zip Contains:**

- FTDX101\_DISPLAY\_V0102.SFL
- FTDX101\_IFDSP\_V0104.SFL
- FTDX101\_MAIN\_V0107.SFL
- FTDX101\_SDR\_V0112.SFL
  
- FTDX101D Firmware Upgrade Manual.pdf
- Important Changes.pdf


### **Implements improvements**

1. The antenna connector "ANT 3/RX" on the transceiver rear panel may be configured to receive only, with "ANT 1" connector or "ANT 2" connector utilized for transmit.
2. The antenna terminal to which an external antenna tuner is connected may be selected.
3. "3500Hz" and "4000Hz" settings are added to the filter bandwidth of the WIDTH function in SSB mode.  
\* Only the SSB mode WIDTH settings are changed.
4. The AMC function that automatically adjusts the audio level so that distortion does not occur even with excessive audio input now always works. (In SSB / PSK / DATA / AM mode operation)
5. Fixed the problem of a "pop" sound that was introduced to the receiver at the end of a transmission using VOX.
6. Corrected an intermittent readout failure of the MAIN band S meter under certain conditions.
7. We have made other functional improvements and optimizations.

## **SD Card Preparation**

Refer to FTDX101D Operation Manual Page 76

After the SD card is formatted and the updated files are installed onto the SD card, it should be displayed like the below image:



If you already have the above firmware versions, it is not necessary to update the FTDX101D again.

We hope this new firmware will increase your enjoyment of your FTDX101D. Thank you for choosing Yaesu radios. If you have any problems or questions, please contact Yaesu Amateur Tech Support [amateurtech@yaesu.com](mailto:amateurtech@yaesu.com).